

2016 WATER QUALITY REPORT FOR HAZLETON WATER SUPPLY

This report contains important information regarding the water quality in our water system. The source of our water is groundwater. Our water quality testing shows the following results:

| CONTAMINANT | MCL - (MCLG) | Compliance | | Date | Violation | Source |
|-----------------------------|-------------------------|------------|--|------------|-----------|---|
| | | Type | Value & (Range) | | | |
| Lead (ppb) | AL=15 (0) | 90th | 5.33 (1 - 167) 1 sample(s) exceeded AL | 2015 | No | Corrosion of household plumbing systems; erosion of natural deposits |
| Copper (ppm) | AL=1.3 (1.3) | 90th | 0.537 (0.169 - 0.820) | 2015 | No | Corrosion of household plumbing systems; Erosion of natural deposits; Leaching from wood preservatives |
| 950 - DISTRIBUTION SYSTEM | | | | | | |
| Chlorine (ppm) | MRDL=4.0 (MRDLG=4.0) | RAA | 2.1 (ND - 2.2) | 09/30/2016 | No | Water additive used to control microbes |
| 01 - FINISHED WATER TAP, #3 | | | | | | |
| Gross Alpha, inc (pCi/L) | 15 (0) | SGL | 2.7 | 07/02/2012 | No | Erosion of natural deposits |
| Combined Radium (pCi/L) | 5 (0) | SGL | 1.7 | 07/08/2015 | No | Erosion of natural deposits |
| Fluoride (ppm) | 4 (4) | SGL | 1.12 | 07/05/2012 | No | Water additive which promotes strong teeth; Erosion of natural deposits; Discharge from fertilizer and aluminum factories |
| Barium (ppm) | 2 (2) | SGL | 0.0414 | 07/05/2012 | No | Discharge of drilling wastes; Discharge from metal refineries; Erosion of natural deposits |
| Sodium (ppm) | N/A (N/A) | SGL | 23.1 | 10/06/2016 | No | Erosion of natural deposits; Added to water during treatment process |

Note: Contaminants with dates indicate results from the most recent testing done in accordance with regulations.